

Notification Regarding Addition of Safety Label Concerning Accumulated Matter inside Duct (DFL7000 Series)

Addition of safety label

In future, the following safety label will be added to shipped laser saws (applicable models: DFL7020, DFL7160, DFL7161, and DFL7560V).



This label is a warning that urges operators to remove accumulated matter between the processing point nozzle and exhaust duct at 7-day intervals in order to prevent fires.

- In addition to English/Japanese labels, English/Chinese (traditional), English/Chinese (simplified), and English/Korean labels are also available.

- See Technical Newsletter

"Request to Perform Periodic Maintenance on Models That Use Protective Film Solution" (#tnl2016-0031e)

In the case of machines that have already been shipped, a DISCO customer engineer will visit you and affix the label in the appropriate position (see next page).

Inquiries

For inquiries regarding this matter, please contact a DISCO sales representative or customer engineer.

Technical Newsletter


#tn12017-0009e

2 / 2




Label position


DFL7160



DFL7161



DFL7020



DFL7560V

