

Technical Newsletter

#tnl2019-0017e

1 / 1



6000/600 Series For 300 mm Wafers Production Discontinuation of UV Lamps

Notice

Production of the UV lamps in use with the UV irradiation unit [optional accessory] has been discontinued. Because of this, we change to new-type UV lamps. The UV lamps to be installed in the machines and those to be sold as maintenance parts will be changed to new-type starting from around March 2020.

Applicable model

Series	Applicable model
6000 series	DFD6350/DFD6360/DFD6360A/DFD6361/DFD6362/DFD6560/DFD6561
600 series	DFD660/DFD670

Changes

- The mark to be printed on the main body changes.
- There is no change in the effects of UV irradiation or the rating life.

	Existing type (production discontinued)	New type
Mark		
Parts No.	DEAFL15UV01-0	DEAFL15BL03-0

Replacement

When replacing any UV lamp, be sure to replace all the UV lamps in use with the UV irradiation unit [optional accessory] by the new-type ones.

For the type and number of UV lamps and the replacement procedure, refer to the Maintenance Manual included with the machine.

Inquiries

Please contact your local DISCO sales representative or DISCO customer engineer if you have any questions regarding this matter.
